3 <sup>1</sup> / <sub>8</sub> "	80mm —				— 80mm	3 <sup>1</sup> / <sub>8</sub> "
2 <sup>3</sup> / <sub>4</sub> "	70mm —				— 70mm	2 <sup>3</sup> / <sub>4</sub> "
2 <sup>3</sup> / <sub>8</sub> "	60mm —				— 60mm	2 <sup>3</sup> / <sub>8</sub> "
2"	50mm —				— 50mm	2"
1 <sup>5</sup> / <sub>8</sub> "	40mm —				— 40mm	1 <sup>5</sup> / <sub>8</sub> "
1 <sup>1</sup> / <sub>8</sub> "	30mm —		Focus on the centre of the thick black line in the box below from an angle of 45 degrees.		— 30mm	1 <sup>1</sup> / <sub>8</sub> "
<sup>3</sup> / <sub>4</sub> "	20mm —		angle of 40 degrees.		— 20mm	<sup>3</sup> / <sub>4</sub> "
<sup>9</sup> / <sub>16</sub> "	14mm —				— 14mm	<sup>9</sup> / <sub>16</sub> "
3/8"	10mm —				— 10mm	<sup>3</sup> / <sub>8</sub> "
15/ <sub>64</sub> "	6mm —				— 6mm	15/ <sub>64</sub> "
<sup>5</sup> / <sub>64</sub> "	2mm —				— 2mm	<sup>5</sup> / <sub>64</sub> "
This text should be perfectly in focus		cus	Focus here	This	s text should be perf	ectly in focus
<sup>5</sup> / <sub>64</sub> "	2mm —				— 2mm	<sup>5</sup> / <sub>64</sub> "
15/ <sub>64</sub> "	6mm —				— 6mm	<sup>15</sup> / <sub>64</sub> "
<sup>3</sup> / <sub>8</sub> " <sup>9</sup> / <sub>16</sub> "	10mm —				— 10mm	<sup>3</sup> / <sub>8</sub> " <sup>9</sup> / <sub>16</sub> "
	14mm —				— 14mm	/16
3/4"	20mm —				— 20mm	<sup>3</sup> / <sub>4</sub> "
1 <sup>1</sup> / <sub>8</sub> "	30mm —		Focus test chart V2.00 Copyright Tim Jackson 2004 tim@FocusTestChart.com http://FocusTestChart.com		— 30mm	1 <sup>1</sup> / <sub>8</sub> "
1 <sup>5</sup> / <sub>8</sub> "	40mm —				— 40mm	1 <sup>5</sup> / <sub>8</sub> "
2"	50mm —				— 50mm	2"
2 <sup>3</sup> / <sub>8</sub> "	60mm —				— 60mm	2 <sup>3</sup> / <sub>8</sub> "
2 <sup>3</sup> / <sub>4</sub> "	70mm —				— 70mm	2 <sup>3</sup> / <sub>4</sub> "
3 <sup>1</sup> / <sub>8</sub> "	80mm —				— 80mm	3 <sup>1</sup> / <sub>8</sub> "